

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA, CALIF.

No. 110543

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080123-7

RECEIVED FROM

DATE REC'D 1-26-57
P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPN. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	S.O. NO.	REMARKS
QUANTITY RECEIVED											
1	322	000000	22061	0	0	00	00				
			DRAWING NO. AND DESCRIPTION								
			732659 COVER					1 ✓			
			SHIP MEMO 33900								

REJECTS RETURNED
ON SHIP. MEMO NO.RECEIVED BY
HMC-1069

INSPECTED BY

Dura

DATE

1/28/57

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA, CALIF.

No. 11058

RECEIVED FROM

DATE REC'D 1/28-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO
QUANTITY RECEIVEDBUY OUT CODE NO.
ACCT. OR W.O. NO.
S.O. NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPN. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	S.O. NO.	REMARKS
QUANTITY RECEIVED											
3	322	000000	22051								
			DRAWING NO. AND DESCRIPTION								
			73831-1 22052 Bearing Retainer					3 ✓			
			SHIP #33937								
			TO Supersede #1102								

REJECTS RETURNED
ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080123-7

RECEIVED BY

INSPECTED BY

Dura

DATE

1/28/57

HMC-1069